

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY SUPERFUND SITE STRATEGY RECOMMENDATION - REGION 06



Site Name: FM 1585 and Avenue L Ground Water	CERCLIS ID#: TXN000606862
Alias Site Name: Country Squire Mobile Home Park	·
Address: 13010 Avenue L	
City/County or Parish/State/Zip: Lubbock/Lubbock County/Texas/79423	-
Report Type: Preliminary Assessment Date: May 30, 2008	Author: David Cullen - TCEQ
RECOMMENDATION:	
Under Superfund (NFRAP) PA SI ESI Other:	stigation Needed Under Superfund HRS Priority: High RI/FS Low RA
To be performed to: RCRA NRC 3. Action Deferred to: RCRA NRC 4. Site Being Addressed Under the State Voluntary Cleanup Program (VC	
NOTIFY AUTHORITY:	
☐ Removal ☐ RCRA ☐ TSCA ☐ CAA ☐ Remedial ☐ State/Tribe ☐ NPDES ☐ NRC ☐ CERCLA ☐ Federal ☐ UIC ☐ SPCC Enforcement Facility	SMCRA Resource Trustee: Other:
SEND SSSR COPIES TO: GSF-AC GWQ-SP ATSDR	
DYCOLOGION	
The indicator well for the FM 1585 and Avenue L Ground Water site (a.k.a. Co on FM 1585 just west of its intersection with U.S. Highway 87. More specifica 2.5-acre parcel of land at 13010 Avenue L in Lubbock, Texas. The indicator w 1520142) which provides water to the Country Squire Mobile Home Park and According to a file review, 1,2-dichlorobenzene has been detected at concentra ug/L in 2007. The MCL for 1,2-dichlorobenzene is 600 ug/L. Source(s) of the identified; however, potential sources are located nearby.	ally, the well is located on an approximately well is a public water supply well (PWS ID# serves a population of approximately 60. ations ranging between 1.38 ug/L and 1.52
The site is located in a commercial and residential mixed community. The land commercial businesses such as boat and vehicle storage facilities, convenience and agricultural. The closest residences located off-site are approximately 100 were observed in the yards of some of these residences and at a dry-cleaning drawll was noted approximately 100 yards northwest of the site. A day care facility school is Cooper Elementary School located approximately 2.5 miles south of	e stores, vehicle repair facilities, food outlets, by yards south of the site. Private water wells rop-off location. The nearest private water lity was observed approximately 250 yards to y during the inspection. The nearest listed the site.
A search of the TCEQ water well database identified 22 wells (including the si Five of these wells are active public water supply wells located within 0.5 miles active public supply wells within 0.5 miles of the site is 1,725.	

Based on the information presented in the Preliminary Assessment report, it is recommended that a Site Inspection be performed at this site. The State will be provided a copy of this decision document.				
•		•		
APPROVALS:				
Report Reviewed by:	Bret Kendrick	Signature: Sum Kanada	Date: 07/15/08	
	(Site Assessment Manager)			
Disposition Approved by:	Jon Rauscher	Signature: Jus Runa	Date: 07/15/08	

(Team Leader 6SF-TR)